



9 OF THESE TOP 10* CODES CAN BE DIAGNOSED WITH THE SMOKE WIZARD™

TOP 10 TROUBLE CODES

- P0325 ➔ Knock Sensor 1 Circuit Bank 1 or Single Sensor
- P0420 ➔ Catalyst System Efficiency Below Threshold Bank 1
- P0300 ➔ Random/Multiple Cylinder Misfire Detected
- P0171 ➔ System Too Lean Bank 1
- P0401 ➔ Exhaust Gas Recirculation Flow Insufficient Detected
- P0174 ➔ System Too Lean Bank 2
- P0455 ➔ Evaporative Emission System Leak Detected (large leak)
- P0442 ➔ Evaporative Emission System Leak Detected (small leak)
- P0301 ➔ Cylinder 1 Misfire Detected
- P1456 ➔ Manufacturer Specific

mySCANNER

888-668-6080 CALL NOW FOR SPECIAL PRICING